From: Stephen Best
To: Flock Safety; Libby Landers; brendon.norton@flocksafety.com; Jake Sherman
Cc: Michael Balcorta; Daniel Cohen; Eligio Lara; Tee Jane Teh; Stephen Best
Subject: And even more failures to read night plates
Date: Friday, May 24, 2024 6:35:38 AM
Attachments: 008 2 hours of cam 134 only 10 plates.pdf
009 2 hours of cam 088 only 80 plates.jpg
001 night read fails 052424 37 percent.jpg
002 night read fails 052424 37 percent ZERO CONFIDENCE.jpg
003 all images cam 001 0512-0514 hrs.jpg
004 all images cam 088 0514-0516 Hrs.jpg
005 all images Cam 090 0515-0518 hrs.jpg
006 all images CAm 028 0516-0519 Hrs.jpg
006 all images CAm 028 0516-0519 Hrs.pdf
007 all images cam 134 0518-0520 hrs.jpg
008 2 hours of cam 134 only 10 plates.jpg

Flock Safety Support,
I tested additional cameras for their ability to read license plates at night.
Of the 8 cameras I passed only 3 read my plate. That's about 37% success rate.

So this week, I've basically driving the width and length of the city four times and 80% of the Flock cameras I passed did not record my plate.

Today's test 05-24-24
CA/ 8LDA954
05:13:19 Hrs. Cam "001 SB Broadway (S of Taylor)" in lane 2 – Failed to read plate
05:14:00 Hrs. Cam "#01 SB N Broadway" (Big America's camera) in lane 2 -Success
05:15:20 Hrs. Cam "088 SB Broadway (S of Orchard)" in lane 2- Failed to read plate (This is on our main thoroughfare!)
05:16:57 Hrs. Cam "090 SB Broadway (S of Chapel)" in lane 2- Failed to read plate (main thoroughfare)
05:17:49 Hrs. Cam "028 SB Broadway (S of Orange)" in lane 2- failed to read plate (main thoroughfare)
05:19:32 Hrs. Cam "134 WB Stowell (W of Thornburg)" in lane 2- failed to read plate (main thoroughfare)
05:20:10 Hrs. Cam "023 SB Depot (S of Stowell)"- Success
05:22:23 Hrs. Cam "110 SB Thornburg (S of Carmen)" -Success

I searched all 220 cameras for 8LDA954 for 05-24-24 from 0500-0530 Hrs. Results=3 successful reads



I took a closer look at two of the cameras on our main thoroughfare and pulled all images from a 2 hour period 0330-0530 Hrs.
Cam "134 WB Stowell" had 21 images but only 10 plate reads
Cam "088 SB Broadway" @ orchard had 214 images but only 80 plate reads.

Also attached are the "all images" for the various cameras at the times I should have been passing by.
(A second email will have some additional attachments.)

Please add all these cameras to the list to be serviced.

Corporal Stephen L. Best
Santa Maria Police Department
1111 W. Betteravia Rd., Santa Maria, CA 93455
(805)928-3781 X2491
sbest@ci.santa-maria.ca.us
sbest@cityofsantamaria.org

WARNING! The information contained in this transmission is privileged and confidential. It is intended only for the use of the person(s) named above. If you are not the intended recipient, you are hereby notified that any review, dissemination, distribution or duplication of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message and any attachments.